MOBILE MOTORS OTTAWA

Sample 150-Point Pre-Purchase Inspection Report

A clear example of the vehicle details, observations, condition ratings, and purchase guidance included in our inspection reporting.

SAMPLE REPORT — FOR ILLUSTRATION ONLY

Vehicle	2018 Honda Civic EX (sample)	Inspection date	Sample only
VIN	2HGFC2F7●●●●●●●●●	Odometer	112,450 km
Location	Ottawa, Ontario	Inspector	Mobile Motors technician

Sample condition summary

Body & exterior	Monitor	Minor cosmetic wear; no obvious structural damage observed
Tires & brakes	Service soon	Rear tires approaching replacement range
Engine & cooling	Good	Fluid levels acceptable; no active leaks observed
Electrical system	Good	Battery and charging output within test range
Road test	Monitor	Minor vibration noted at highway speed

Sample recommendation

Proceed after review. The sample vehicle appears generally serviceable, with rear tire replacement and further diagnosis of the highway-speed vibration recommended before purchase. This example is not a guarantee, appraisal, safety certificate, or substitute for an inspection of the actual vehicle.

Rating key: Good = operating normally at inspection • Monitor = wear or concern to watch • Service soon = repair or further diagnosis recommended • Not checked = inaccessible, unsafe, unavailable, or not applicable.

Important limitations: This is a visual and functional assessment of accessible components at the time and place of inspection. Weather, access, seller permission, road conditions, diagnostic access, and safety can limit checks. Hidden defects and future failures cannot be guaranteed.

01 Vehicle Identification & Roadworthiness

NO.	INSPECTION POINT	SAMPLE RATING	NOTES
1	VIN matches dashboard and body labels	Good	No concern observed
2	Licence plate and registration details	Good	No concern observed
3	Odometer reading recorded	Monitor	Review condition with buyer
4	Warning lights illuminate during bulb check	Good	No concern observed
5	Warning lights clear after startup	Good	No concern observed
6	Owner's manual present	Good	No concern observed
7	Service records reviewed when available	Good	No concern observed
8	Recall history discussed	Monitor	Review condition with buyer
9	Number of keys and remotes recorded	Good	No concern observed
10	Exterior mirrors secure	Good	No concern observed
11	Horn operation	Good	No concern observed
12	Windshield washer operation	Good	No concern observed
13	Wiper blade condition	Monitor	Review condition with buyer
14	Parking brake operation	Good	No concern observed
15	General roadworthiness observations	Good	No concern observed

02 Body, Frame & Exterior

NO.	INSPECTION POINT	SAMPLE RATING	NOTES
16	Front bumper condition	Good	No concern observed
17	Rear bumper condition	Monitor	Review condition with buyer
18	Hood alignment and operation	Good	No concern observed
19	Trunk or liftgate operation	Good	No concern observed
20	Driver-side body panels	Good	No concern observed
21	Passenger-side body panels	Good	No concern observed
22	Roof and pillars	Monitor	Review condition with buyer
23	Door alignment and hinges	Good	No concern observed
24	Visible frame or unibody damage	Good	No concern observed
25	Signs of previous collision repair	Good	No concern observed
26	Paint consistency and overspray	Good	No concern observed
27	Exterior rust or corrosion	Monitor	Review condition with buyer
28	Fuel door and fuel cap	Good	No concern observed
29	Body seals and weatherstripping	Good	No concern observed
30	Underbody splash shields	Good	No concern observed

03 Glass, Lights & Visibility

NO.	INSPECTION POINT	SAMPLE RATING	NOTES
31	Windshield chips and cracks	Monitor	Review condition with buyer
32	Rear glass condition	Good	No concern observed
33	Side glass condition	Good	No concern observed
34	Power window operation	Good	No concern observed
35	Window tint condition and visibility	Good	No concern observed
36	Headlights — low beam	Monitor	Review condition with buyer
37	Headlights — high beam	Good	No concern observed
38	Daytime running lights	Good	No concern observed
39	Front turn signals	Good	No concern observed
40	Rear turn signals	Good	No concern observed
41	Brake lights	Monitor	Review condition with buyer
42	Tail lights	Good	No concern observed
43	Reverse lights	Good	No concern observed
44	Hazard lights	Good	No concern observed
45	Exterior camera and sensor lenses	Good	No concern observed

04 Tires, Wheels & Brakes

NO.	INSPECTION POINT	SAMPLE RATING	NOTES
46	Left-front tire tread depth	Good	No concern observed
47	Right-front tire tread depth	Good	No concern observed
48	Left-rear tire tread depth	Good	No concern observed
49	Right-rear tire tread depth	Good	No concern observed
50	Tire age and sidewall condition	Monitor	Review condition with buyer
51	Tire size and type match	Good	No concern observed
52	Spare tire or mobility kit	Good	No concern observed
53	Wheel and rim condition	Good	No concern observed
54	Wheel fasteners present	Good	No concern observed
55	Front brake pad condition	Monitor	Review condition with buyer
56	Rear brake pad condition	Good	No concern observed
57	Brake rotor condition	Good	No concern observed
58	Brake hydraulic lines	Good	No concern observed
59	Brake fluid level and condition	Good	No concern observed
60	Brake pedal feel and stopping behaviour	Monitor	Review condition with buyer

05 Steering, Suspension & Undercarriage

NO.	INSPECTION POINT	SAMPLE RATING	NOTES
61	Steering wheel free play	Good	No concern observed
62	Power steering operation	Good	No concern observed
63	Tie rods and steering linkage	Good	No concern observed
64	Front ball joints	Monitor	Review condition with buyer
65	Rear suspension joints	Good	No concern observed
66	Front struts or shocks	Good	No concern observed
67	Rear struts or shocks	Good	No concern observed
68	Coil springs and mounts	Good	No concern observed
69	Control arms and bushings	Monitor	Review condition with buyer
70	Wheel bearing noise or play	Good	No concern observed
71	CV boots and joints	Good	No concern observed
72	Driveshaft and universal joints	Good	No concern observed
73	Subframe and mounting points	Good	No concern observed
74	Underbody rust or impact damage	Monitor	Review condition with buyer
75	Ride height and vehicle stance	Good	No concern observed

06 Engine & Cooling System

NO.	INSPECTION POINT	SAMPLE RATING	NOTES
76	Engine oil level	Good	No concern observed
77	Engine oil condition	Good	No concern observed
78	Visible engine oil leaks	Monitor	Review condition with buyer
79	Coolant level	Good	No concern observed
80	Coolant condition	Good	No concern observed
81	Radiator condition	Good	No concern observed
82	Cooling fan operation	Good	No concern observed
83	Radiator and heater hoses	Monitor	Review condition with buyer
84	Drive belts and tensioners	Good	No concern observed
85	Engine mounts	Good	No concern observed
86	Air filter condition	Good	No concern observed
87	Intake ducting and clamps	Good	No concern observed
88	Exhaust smoke at startup	Monitor	Review condition with buyer
89	Engine idle quality	Good	No concern observed
90	Abnormal engine noises	Good	No concern observed

07 Transmission, Driveline & Exhaust

NO.	INSPECTION POINT	SAMPLE RATING	NOTES
91	Transmission fluid level when accessible	Good	No concern observed
92	Transmission fluid condition when accessible	Monitor	Review condition with buyer
93	Transmission leaks	Good	No concern observed
94	Automatic shift engagement	Good	No concern observed
95	Shift quality during road test	Good	No concern observed
96	Manual clutch engagement when equipped	Good	No concern observed
97	Transfer case operation when equipped	Monitor	Review condition with buyer
98	Differential leaks	Good	No concern observed
99	Axle seals	Good	No concern observed
100	Exhaust manifold condition	Good	No concern observed
101	Exhaust pipes and joints	Good	No concern observed
102	Catalytic converter exterior condition	Monitor	Review condition with buyer
103	Muffler and resonator condition	Good	No concern observed
104	Exhaust hangers and heat shields	Good	No concern observed
105	Abnormal driveline vibration	Good	No concern observed

08 Electrical, Starting & Charging

NO.	INSPECTION POINT	SAMPLE RATING	NOTES
106	Battery physical condition	Monitor	Review condition with buyer
107	Battery terminal condition	Good	No concern observed
108	Battery state-of-health test	Good	No concern observed
109	Battery state-of-charge test	Good	No concern observed
110	Engine cranking performance	Good	No concern observed
111	Starter operation	Monitor	Review condition with buyer
112	Charging system output	Good	No concern observed
113	Alternator noise	Good	No concern observed
114	Fuse and relay box condition	Good	No concern observed
115	Interior lighting	Good	No concern observed
116	Power outlet operation	Monitor	Review condition with buyer
117	Infotainment system	Good	No concern observed
118	Instrument cluster display	Good	No concern observed
119	Keyless entry and remote functions	Good	No concern observed
120	Visible wiring modifications	Good	No concern observed

09 Interior, Comfort & Safety

NO.	INSPECTION POINT	SAMPLE RATING	NOTES
121	Driver seat condition and adjustment	Good	No concern observed
122	Passenger seat condition and adjustment	Good	No concern observed
123	Rear seat condition	Good	No concern observed
124	Seat belt condition and operation	Good	No concern observed
125	Airbag indicator self-check	Monitor	Review condition with buyer
126	Child-seat anchor condition	Good	No concern observed
127	Door lock operation	Good	No concern observed
128	Heating system operation	Good	No concern observed
129	Air-conditioning operation	Good	No concern observed
130	Blower fan speeds	Monitor	Review condition with buyer
131	Defroster operation	Good	No concern observed
132	Dashboard and interior trim	Good	No concern observed
133	Headliner and carpet condition	Good	No concern observed
134	Signs of water intrusion	Good	No concern observed
135	Cabin odour or smoke evidence	Monitor	Review condition with buyer

10 Road Test & Final Assessment

NO.	INSPECTION POINT	SAMPLE RATING	NOTES
136	Cold start behaviour when available	Good	No concern observed
137	Engine acceleration response	Good	No concern observed
138	Transmission response	Good	No concern observed
139	Vehicle tracks straight	Monitor	Review condition with buyer
140	Steering response and centring	Good	No concern observed
141	Brake performance	Good	No concern observed
142	ABS activation warning check	Good	No concern observed
143	Suspension noise over bumps	Good	No concern observed
144	Body vibration or rattles	Monitor	Review condition with buyer
145	Cruise control operation when safe	Good	No concern observed
146	Speedometer operation	Good	No concern observed
147	Odometer operation	Good	No concern observed
148	Temperature gauge stability	Good	No concern observed
149	Post-road-test leak check	Monitor	Review condition with buyer
150	Overall purchase recommendation	Good	No concern observed